	r ID 102115 2013 10:23:22 AM		*102115*					
Revision ID:	D4021-5 Blanking Plate	7	Accept	*N90004010	Setup Start Stop	*NS1* *NS2*		
Required Date: 5/	5/27/2013 Start Qty: 5/29/2013 Req'd Qty: PAINT BLACK SANDTE	2.00 *2*	:	Cust Item ID: Customer:		14.57		
	Process Plan: \times \text{OW} QC:	Date: 55	Tooling: SPC (Y/N):	Date:	Run Start Stop	*NR1* *NR2*		
Sequence ID/ Work Center ID			Set Up/ Run Hours	Tool ID Tool # Plan Code	•	Reject Insp. Jumber Stamp		
Draw Nbr	Revision Nbr	;		,				
D4021	В				,			
60 *160* -landFinish	: Me	mo.	0.00		200	Sf 13-5.		
land Finishing		RIP PAINT AND R E ALGEIR	E		,			
70 1170*	QC7-Inspect Ch	emical Conversion Coat	0.00		N/A			
QC . uality Control	Me	mo	0.00		·			
₃₀ :18∩*	Black Sandtex(F	Ref:4.3.5.7) per QSI005 4.3	0.00	actione : 2:	33 2 V 6	m /17/		
Powdercoat owder Coating	Me	mo	0.00	emp : 3200	F ~ N N D / 1	m-f-15/05/		
	3480		£.	nish Time: 300	1)			

Quality Control

Monday, May 27, 2013 10:23:21 AM

Work Order ID:

102115

Parent Item:

D4021-5

Parent Item Name:

Blanking Plate

Start Date: 5/27/2013

Required Date: 5/29/2013

Start Qty: 2.00

Required Qty: 2.00

Comments:

IPP RevA: new issue DD 09.11.25 verified by:EC 10.02.22 verified by:EC IPP Rev.C as per dwg

IPP Rev:B as per dwg REV.A DD

	·	10.02.22 verified i	by:EC IPP Re	v:C as pe	r dwg revB Di	J 10.04.20 ver	ified by:EC	•						
Comp Item N		Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D4021-			Manufactured	j No				Each	6.0000		2			
Blankir	ng Plate										_			

Location Loc Qty Loc Code ST084

X2 yrux (35-27